

CERTIFICATE

Welding of railway vehicles and components according to:
EN 15085-2

This Certificate is issued to: **INDUSTRIAS MECÁNICAS JOPENSA, S.L.**
C/ Industria s/n, 46610 Guadassuar. Valencia. España

Is qualified to perform welding work within the range of certification of

Certification Level CL1 according to EN 15085-2:2020
Type of activity: P

Type of components: **Manufacturing of welding components to railway sector, according
EN 15085-2.**

Welding processes and base material groups:

Welding process according to EN ISO 4063	Material group according to CEN ISO/TR 15608	Dimensions	Comments
135	1.2-10.1 1.2 1.2 8.1 8.1 2.2	2-16 mm 2-40 mm 1-4-4 mm/3-16 mm ≥3 mm/10-40 mm 1.5-40 3-12 mm 3-20 mm	FW BW FW sl BW, T-joint Automatic BW, automatic BW/FW, partly mechanized BW
141	10.1 10.1 10.1/8.1 8.1 8.1/1.2	1-6 mm 1-8 mm 1.4-80 mm 1-20 mm 1.5-24 mm	BW FW FW FW FW

Responsible welding coordinator (RWC): Sergio Moldero (External-Level A)
Deputy welding coordinator (DWC): Rafael Masip Roig (Level C)
Comments: see reverse.

Born: 1979
Born: 1979

Certificate No: LRQA/15085/CL1/264/OA3/24
Valid: from 5 March 2024 to 30 June 2025
Issued on: 5 March 2024
Auditor: Vicente Rouco

Juan Antonio Pozo

Head of MCB

General regulations (see annex)

Annex certificate No: LRQA/15085/CL1/264/OA3/24

INDUSTRIAS MECÁNICAS JOPENSA, S.L.
C/ Industria s/n, 46610 Guadassuar. Valencia. España

Comments:

This Certificate is subject to monitoring of compliance by LRQA Inspection Iberia, S.A. as required by the standard EN15085-2: 2020.

RWC Sergio Moldero (IWT-ES-280), assessed for qualification of welders and welding procedures under the scope of this certification.

Small manufacturer with a single welding shop.

General regulations

according to EN 15085-2: 2020

Revocation of the Certificate

The manufacturer certification body issuing this certificate may revoke the certificate if:

- there are justified doubts as to the proper execution of the welding work according to the stated standards,
- there are justified doubts as to the proper welding coordination according to the stated standards,
- no recognized welding coordinator is available any longer,
- no valid qualification test certificates for the welders and welding operators according to the specified standards are available,
- welders or welding operators without tested qualifications have been entrusted with the execution of welding work under the stated standards,
- other conditions according to the stated standards are no longer satisfied,
- the manufacturer certification body was refused an opportunity to perform the annual verification,
- the welding manufacturer waives the certificate

The welding manufacturer shall acknowledge the revocation in writing to the manufacturer certification body.

If a valid certificate is to be renewed, the renewal must be applied for with the manufacturer certification body at least three months before the end of the period of validity of the current certificate.

Distribution list:

1. Applicant (original- Email)
2. LRQA Inspection Iberia Madrid